Figure 1-4 - Horsley Park Plant 2 Upgrade Environmental Status Report

SITE: Horsley Park Plant 2

Person(s) inspecting: MAL MELLOWS

Date: 26.11.20

Person(s) consulted: CASS STEPACHER/MATT JACKSON

INSPECTION ITEM	REFERENCE (and inspection details)	(Yes- No- N/A)	Issues or comments (Must complete if changes have occurred or non-compliance issues- Hazard must be opened for any issue or incident *see Hazard Reporting and Risk Control ~ SHE-MSP-All-06.001*	Eg. Hazard form (No.) OR Toolbox meeting (date)
GENERAL	Current progress of Construction / Demolition work			mounty (cute)
	Have any changes occurred to Submitted Plans?	NO		
	If so, should new checks be added or existing checks modified?	NA		
	Any checks for new licence/permit/approval conditions be added to this list?	No	/	
	Has there been any Increased risk of hazard / fire?	20		
	Traffic Management – Is Traffic moving smoothly as designed?	455		
DISPOSAL	SHE-MSP-Env-07.004	1.70	A-1	
	Have any hazardous substances been correctly disposed of?	465	MAT'L MOUTH TO CONTAIN	MENT CELL
	Have waste transport certificates been completed and retained on file?	425	ASBESTOS WASTE RELE	PK ON FI
	Have any materials containing Asbestos been disturbed?	455	DURING BEMOVAL.	7
	Has it been handled according to Australian Standards?	423.	HUNTER WEST SWMS	•
	Has any Asbestos been disposed off?	453.	AS AGONE	
	Has it been disposed of to standard and have waste transport certificates been completed and retained on file?	455	AS ABOVE	r i gilan
POLLUTION	SHE-MSP-Env-07.332			
14	Is all pollution control equipment operating correctly?	NA		
	Is maintenance, emptying or replenishment required?	NA		
	Are any additional pollution controls required?	40		
	SHE-MSP-Env-07.342			7776
	Are spill kits appropriately stocked and located?	YES	C / 1/4 C / 1/4 C / 1/4 C / 1/4 C	
	Are hydrocarbons stored correctly in bunds (or on bunded pallets)?	YES		1 4
	Have all lids, caps, and bungs been refitted after use? Are empty hydrocarbon containers stored so as to not fill-up with rain?	455		
WASTE	SHE-MSP-Env-07.334	,,,,		
WACIE	Are initiatives to reduce waste functioning successfully?	NA	NON DRELATIONAL SITE	_
	Is any excess waste being generated?	NO	NON GREGITIONIC SITE	
	Is waste being separated for re-use or recycling where possible?	YES	CRN WASTE/STEEL/C	offel
	Is re-usable or recyclable waste being stored appropriately?	YES		
	Are all bins, skips, bunkers and stockpiles clearly labelled?	YES		
	Is waste for disposal stored correctly and removed regularly?	YES		
WATER	SHE-MSP-Env-07.335	1-3		
	Have there been significant storms or rainfall events?	YES		
	Is stormwater flowing as designed?	YES		
	Are all drains and grates clear of blockages?	YES		
	Is surface water being correctly separated, directed and/or contained?	YES		
	Are all Erosion Sedimentation Controls in place& operating as required?	YES		
	Are additional sediment or other controls required?	NO		
	Does pond, sump or surface water require treatment prior to discharge?	400	avarry Dam	
	Are preventative measures being implemented to avoid poor water quality? Have any controlled or uncontrolled discharges been	46)	Waty treatment	
	Have any controlled or uncontrolled discharges been monitored? Are all waste treatment or sewage (porta-loo) systems	Yes	through EPH Point 1	
	operating correctly? SHE-MSP-Env-10.335	YES	PUMPED FOLTNIGHTLY	
		yes		
	Have water samples been collected as required? Are enough empty sample bottles on hand for prolonged	Yes		

INSPECTION ITEM	REFERENCE (and inspection details)	(Yes- No- N/A)	Issues or comments (Must complete if changes have occurred or non- compliance issues- Hazard must be opened for any issue or incident *see Hazard Reporting and Risk Control ~ SHE-MSP-All-06.001*	Action Taken Eg. Hazard form (No.) OR Toolbox meeting (date)
LAND	SHE-MSP-Env-07.336	36.75		
	Has any Unexpected Contamination been discovered on site?	No		
	If yes Has the contamination procedure been followed?			
	Has any Aboriginal Heritage been discovered?	NO	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
	If yes Has the Aboriginal Heritage finds procedure been followed?	-		
	Is landscaping, re-vegetation or rehabilitation recommended?	NO	Eastern Creek Rehaus	
	Do fences and gates prevent vehicle/person/animal access as appropriate?	Yes		
AIR	SHE-MSP-Env-07.321			
	Are existing dust suppression controls	yes		
	(sweeping/watercart/etc) effective? Are raw materials stored to avoid becoming spilt and/or			
	windblown?	yes		
	Are material transfer processes successful in minimising dust and spillage?	yes		
	SHE-MSP-AII-10.021			
	Are meteorological data & significant dust-creating activities recorded?	Yes	Onsile Weather Stati	On.
	Is any dust potentially escaping off-site?	NO		
NOISE	SHE-MSP-Env-07.322	the Training		
	Any work outside proscribed operating hours?	NO		
	SHE-MSP-AII-10.022			
	Are there are any potential off-site noise impacts?	NO		
BULK LIQUID	SHE-MSP-Env-07.337			
STORAGE	Are all liquid containers stored appropriately in suitable locations?	NA	NIL onsite	
	Are all above-ground tanks double-skinned or adequately bunded?	NA	NIL onsit	
	Are full IBC's stored in appropriate locations away from drains/waterways?	NA		
	Are damaged, faulty or dis-used IBC's being promptly removed from site?	NA	,	
COMPLAINTS & REPORTS	SHE-MSP-Env-03.331			
	Have any complaints been recorded and investigated?	NIL		
	Have any incidents occurred?	NIL		
	Have any incidents been reported to regulators as required?	NIL	1 1 2	